

## INFORMATION BULLETIN

No.: V 510/1b

**Refers to:** Aircraft propellers of the V 510 type Maintenance Manuals. Discard the work

procedure chart 061.20.01 page 305-306 "Screw the tightening of the governor

"V" microswitch"

**Reason:** Due to the request of the governor LUN 7816-8 manufacturer Jihostroj Velešín

documented by his experience in the service and overhaul activities which were

done on the similar type of governor LUN 7815.01 and LUN 7815.02.

**Measures:** Users discard from the Maintenance manuals the following pages:

- List of amendments, page 1

- List of affective pages, page 1, 4, 5

061.20 - Contents, page 1, 2 061.20.01 - page 305, 306

and insert pages dated 1.1. 1987 enclosed to this bulletin.

**To be carried out:** By the user.

**Costs:** No costs arise.

Material: New pages enclosed.

**Bulletin comes in force:** By the date of SLI approval.

In Prague on December 1, 1987

M. Adamec m. p. Ing. B. Homola m.p.

Manufacturer's Representative Customer's Representative at the Manufacturer

Ing. K. Sovák. ing. J. Toman m. p.
OMNIPOL State civil aviation inspection

Page 1